Case Study



General Information

Location	West Dublin
Number of Units	110
Apartment size	72 m2
No. of Wetrooms	K + 2
Product Status	Victorum 150L

Floor U-valve (W/m²K)	NA
Roof U-valve (W/m²K)	NA
Wall U-valve (W/m²K)	0.18
Window U-valve (W/m²K)	1.2
Window G-valve	NA
Thermal Bridging (W/m²K)	0.15
Air Permeability (m³/hr/m²)	NA





Case Study




System Selection

Selection of houses, duplexes & apartments all built and finished to the highest standards.

Adress

Lucan, Co. Dublin



For more information visit:



www.joule.ie

